Chart 6
A Systematic Approach to Problem Well Tests Without Weight Measurements